


CORNER RECORD

Document Number 3527-34-96

City of MAMMOTH LAKES

County of MONO, California

Brief Legal Description CENTERLINE MONUMENTS, MAMMOTH VISTA NO. 3, S34, T.3S, R.27E
MD B & M



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☐
Rancho ☐ Other ☒
Date of Survey 8-13-98

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FND 2" IRON PIPE PER MB 9/33 @ THE EC NORTHEAST OF LOT 35.
TIED OUT

A description of the physical condition of the monument as found and as set or reset: SET 2" PK & WASHER
"LS 4587" AS A DIRECT REPLACEMENT OF 2" IRON PIPE FND PER MB 9/33 @ THE EC
NORTHEAST OF LOT 35. DESTROYED DURING ROAD CONSTRUCTION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on January 21 1999.

Signed [Signature] L.S. or R.C.E. Number 4587

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-25 1999 and examined and filed 1-29 1999.

Signed [Signature] Title DEPUTY MONO COUNTY SURVEYOR
LIC. EXP. 6-30-00

County Surveyor's Comment _____





NO SCALE

(R) Record Data per
MB 9/33

MB

LOT 11

LOT 10

MAJESTIC PINES DRIVE

9/33
CW

DIRECT REPLACED
FND 2" IP RCE15160
PER MB 9/33
DESTROYED DURING
ROAD CONSTRUCTION
WITH 2" PK & WASHER
"LS4587"

LOT 34

LOT 35

$\Delta = 44^{\circ}10'07''$ $L = 231.27'(R)$
 $R = 300'$

JW 1260